

N83447.AR.000438
NAS FORT WORTH
5090.3a

LETTER RESPONDING TO REGULATORY REVIEW AND APPROVAL FOR NO FURTHER
ACTION AT VISUAL INFORMATION CENTER WORK STATION WASTE ACCUMULATION
AREAS NAS FORT WORTH TX

4/28/1999

TEXAS NATURAL RESOURCE CONSERVATION COMMISSION



**NAVAL AIR STATION
FORT WORTH JRB
CARSWELL FIELD
TEXAS**

**ADMINISTRATIVE RECORD
COVER SHEET**

AR File Number 479

Robert J. Huston, *Chairman*
R. B. "Ralph" Marquez, *Commissioner*
John M. Baker, *Commissioner*
Jeffrey A. Saitas, *Executive Director*



TEXAS NATURAL RESOURCE CONSERVATION COMMISSION

Protecting Texas by Reducing and Preventing Pollution

April 28, 1999

Mr. Michael Dodyk
Restoration Team Chief
HQ AFCEE/ERD
P.O. Box 27008
Fort Worth, TX 76127-0008

RE: NAS/JRB Carswell AFB
TNRCC Solid Waste Registration No. 65004
TNRCC Hazardous Waste Permit No. HW-50289
EPA ID No. TX0571924042
SWMU No.13, Visual Information Center Work Station Waste Accumulation Area
Approval of No Further Action Request Report

Dear Mr. Dodyk:

The Texas Natural Resource Conservation Commission (TNRCC) received your No Further Action Request Report for SWMU 13, dated April 15, 1999. The Report indicated that RFI activities for this unit are not necessary, due to the 1989 RFA recommendation of no further action and determination that there had not been a release and the potential for release is low. Also, the 1996 investigation following unit removal found that the wastes were properly managed and there was no evidence of a release.

The TNRCC has completed a review of the No Further Action Request Report. Based on the information contained in the Report, it appears that No Further Action status is warranted. SWMU 13 is released from RFI requirements.

Please be aware that it is the continuing obligation of persons associated with a site to assure that municipal hazardous waste and industrial solid waste are managed in a manner which does not cause the discharge or imminent threat of discharge of waste into or adjacent to waters in the state, a nuisance, or the endangerment of the public health and welfare as required by 30 TAC §335.4. If SWMU 13 fails to comply with these requirements, the burden remains upon AFCEE to take any necessary and authorized action to correct such conditions. A TNRCC field inspector may review your Report and conduct an inspection of the unit.

Questions concerning this letter should be directed to me at (512) 239-2333. When responding by mail, please submit an original and one copy of all correspondence and reports to the Corrective Action Section at Mail Code MC-127 with an additional copy submitted to the TNRCC Region 4

Mr. Dodyk
Page 2

Office in Arlington. The TNRCC Solid Waste Registration Number and SWMU 13 should be referenced in all submittals.

Sincerely,



Ray S. Rysner, Sr. Project Manager
Team II, Corrective Action Section
Remediation Division

RSR/rsr

cc: Mr. Joe Dunkle, Remedial Program Manager, HQ AFCEE/ERD
3207 North Road, Brooks AFB, TX 78235
Mr. Gary W. Miller, Federal Facility Team, EPA Region VI Office - Dallas
Mr. Sam Barrett, Waste Program Manager, TNRCC Region 4 Office - Arlington

FINAL PAGE

ADMINISTRATIVE RECORD

FINAL PAGE